

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

INDOOR AIR QUALITY MODULE WITH PIVOTAL INNER COMPARTMENT FOR  
SERVICABILITY OF MODULE COMPONENTS

Applicant: Uslenghi et al.; Attorney Docket: 60246-339; Express Mail No. EV235995665US




FIG. 1




FIG. 2






FIG. 3

INDOOR AIR QUALITY MODULE WITH PIVOTAL INNER COMPARTMENT FOR  
SERVICABILITY OF MODULE COMPONENTS  
Applicant: Uslenghi et al.; Attorney Docket: 60246-339; Express Mail No. EV235995665US



INDOOR AIR QUALITY MODULE WITH PIVOTAL INNER COMPARTMENT FOR  
SERVICABILITY OF MODULE COMPONENTS

Applicant: Uslenghi et al.; Attorney Docket: 60246-339; Express Mail No. EV235995665US

3/4




FIG. 7

INDOOR AIR QUALITY MODULE WITH PIVOTAL INNER COMPARTMENT FOR  
SERVICABILITY OF MODULE COMPONENTS

Applicant: Uslenghi et al.; Attorney Docket: 60246-339; Express Mail No. EV235995665US

4/4

